

1		2		3		4		5		6		7		8		9	
REV.	REMARK	DATE		SIGN.													

WIRING DIAGRAM

HIGH SPEED SIGNAL			
P1(Mini SAS HD 4x Plug)		P2(Mini SAS HD 4x Plug)	
PAD	SIGNAL	PAD	SIGNAL
A4	RX1+	C4	TX1+
A5	RX1-	C5	TX1-
A7	RX3+	C7	TX3+
A8	RX3-	C8	TX3-
B4	RX0+	D4	TX0+
B5	RX0-	D5	TX0-
B7	RX2+	D7	TX2+
B8	RX2-	D8	TX2-
C4	TX1+	A4	RX1+
C5	TX1-	A5	RX1-
C7	TX3+	A7	RX3+
C8	TX3-	A8	RX3-
D4	TX0+	B4	RX0+
D5	TX0-	B5	RX0-
D7	TX2+	B7	RX2+
D8	TX2-	B8	RX2-
GND GROUP	GND	GND GROUP	GND
GND GROUP 1: P1-A3,A6,A9,B3,B6,B9, P2-C3,C6,C9,D3,D6,D9			
GND GROUP 2: P1-C3,C6,C9,D3,D6,D9, P2-A3,A6,A9,B3,B6,B9			
CONNECTOR SHELL		CONNECTOR SHELL	

LOW SPEED SIGNAL & POWER			
P1,P2(Mini SAS HD 4x Plug)		SIGNAL	
PAD	SIGNAL		
A1	Reserved		N.C.
A2	IntL		N.C.
B1	Vact		N.C.
B2	ModPrsL		→ GND
C1	SCL		SERIAL EEPROM
C2	SDA		→ GND
D1	Vact		N.C.
D2	Vman		

DESC.	Mini SAS HD 4x*2 FOR SAS 4.0 CABLE ASS'Y	APPROVED	CHECKED	DESIGNED	TOLERANCE	SCALE	*	UNIT	mm	⌀
P/N	B-6681	CUSTOMER P/N			Sino		DATE	12/03/'18	DWG NO:	DWG\B\6681
1	2	3	4	5	6	7	8	9		